

Consolidated maintenance book
 0219 - CML3PH3

Real end	Intervention code	Redefined intervention	Intervention	Observation	Meter reading	U	Main. kind	Closing date	Created on	Voucher code	Voucher state	State	Start expected	Real start	Localization
07/07/2022	Pr-C71-250H-4	Pr-C71-250H	MP-CHERRY-PICKER GENIE Z-6034		1774	H	Preventive maintenance	22/08/2022	02/08/2022	0020-22-214-07	Closed	Done	07/07/2022	07/07/2022	Sudan (0219/0020/PSU)
27/04/2022	0020-22-156-11-A		The installation has been completed and the necessary procedures have been taken	SIV: 0171600	1634	H	Corrective maintenance	11/06/2022	05/06/2022	0020-22-156-11	Closed	Done	27/04/2022	27/04/2022	Road El Farag Corridor (0219/0020/PSU)
05/01/2022	0020-22-078-01-A		The installation has been completed and the necessary procedures have been taken	SIV: 01413105V: 0112000SIV: 0153233	1546	H	Corrective maintenance	20/03/2022	17/03/2022	0020-22-078-01	Closed	Done	05/01/2022	05/01/2022	Road El Farag Corridor (0219/0020/PSU)
27/12/2020	Pr-C71-500H-2	Pr-C71-500H	MP-CHERRY-PICKER GENIE Z-6034		1442	H	Preventive maintenance	17/05/2021	04/03/2021	0020-21-063-07	Closed	Done	27/12/2020	27/12/2020	Sudan (0219/0020/PSU)
27/12/2020	Pr-C71-250H-3	Pr-C71-250H	MP-CHERRY-PICKER GENIE Z-6034		1442	H	Preventive maintenance	17/05/2021	04/03/2021	0020-21-063-07	Closed	Done	27/12/2020	27/12/2020	Sudan (0219/0020/PSU)
23/11/2020	0020-21-067-03-B		HYDRAULIC LEAKAGE	SIV: 0110227	1435	H	Corrective maintenance	17/05/2021	08/03/2021	0020-21-067-03	Closed	Done	23/11/2020	23/11/2020	Sudan (0219/0020/PSU)
14/09/2020	Pr-C71-250H-1	Pr-C71-250H	MP-CHERRY-PICKER GENIE Z-6034		1362	H	Preventive maintenance	03/10/2020	01/10/2020	0020-20-275-03	Closed	Done	14/09/2020	14/09/2020	Sudan (0219/0020/PSU)
04/07/2020	0020-20-209-12-A		STARTING PROBLEM	SIV: 077871	1209	H	Corrective maintenance	17/08/2020	27/07/2020	0020-20-209-12	Closed	Done	04/07/2020	04/07/2020	Kil-Kat (0219/0020/PSU)
25/12/2019	0020-20-065-21-A		LIFTING JACK REPAIR	SIV: 060022000093	1099	H	Corrective maintenance	09/03/2020	05/03/2020	0020-20-065-21	Closed	Done	25/12/2019	25/12/2019	Abu Rawash (0219/0020/PE)
16/03/2019	0020-19-079-09-A		Month equipment inspection - Lifting Team	None	1076	H	Preventive maintenance	16/03/2019	20/03/2019	0020-19-079-09	Closed	Done	16/03/2019	16/03/2019	Nasser (0219/0020/PSU)
17/12/2018	0020-19-020-19-A		Charging system malfunction	SIV: 010818	1060	H	Corrective maintenance	30/01/2019	30/01/2019	0020-19-020-19	Closed	Done	17/12/2018	17/12/2018	Abu Rawash (0219/0020/PE)
16/11/2016	Pr-C70-250h-GENIE-1	Pr-C70-250h-GENIE	Pr-250h-Manitr-GENIE		2385	H	Pr	31/01/2017							
16/11/2016	Pr-C70-500h-GENIE-1	Pr-C70-500h-GENIE	Pr-500h-Manitr-GENIE		2385	H	Pr	31/01/2017							
16/11/2016	Pr-C70-1000h-GENIE-1	Pr-C70-1000h-GENIE	Pr-1000h-Manitr-GENIE		2385	H	Pr	31/01/2017							
08/07/2017	0010-17-189-12-A		joystick broken	change orientation joystick as attached photo	2385	H	Co	13/07/2017							
08/07/2017	0010-17-189-12-B		joystick malfunction	change travelling joystick	2385	H	Co	13/07/2017							
14/06/2017	6M-INSP-3	6M-INSP	6_Month-Inspection	loyds inspection	2385	H	RC	25/07/2017							
21/12/2017	Pr-C70-250h-GENIE-2	Pr-C70-250h-GENIE	Pr-250h-Manitr-GENIE		827	H	Pr	08/01/2018							
21/12/2017	Pr-C70-500h-GENIE-2	Pr-C70-500h-GENIE	Pr-500h-Manitr-GENIE		827	H	Pr	08/01/2018							
21/12/2017	Pr-C70-1000h-GENIE-2	Pr-C70-1000h-GENIE	Pr-1000h-Manitr-GENIE		827	H	Pr	08/01/2018							
21/12/2017	Pr-C70-2000h-GENIE-2	Pr-C70-2000h-GENIE	Pr-2000		827	H	Pr	08/01/2018							
20/02/2018	6M-INSP-4	6M-INSP	6_Month-Inspection		827	H	RC	01/03/2018							
08/08/2018	6M-INSP-5	6M-INSP	6_Month-Inspection	real date: 20/8/2018	827	H	000z' id: 3 code: '3'	29/08/2018							
07/08/2018	0010-18-219-19-A		joystick modification	joystick function modification replaced by an on off switch to dedicate the main issue	827	H	000z' id: 1 code: '1'	24/09/2018							
07/08/2018	0010-18-219-19-B		hydraulic issue	main control valve issue - hydraulic circuit need to be flushed	827	H	000z' id: 1 code: '1'	24/09/2018							